

Contract/ Dispatch	Road	Fault	Start	Length	Width	Programme	Category	Activity
20/25	BAY PADDOCK ROAD	FatigCrack - Digout (Two)	1,894	5	2	006 January 2019		DIGOUTS
20/61	POSTMANS ROAD	FatigCrack - Digout (Two)	2,100	27	6	006 January 2019	NCTIR	DIGOUTS
20/63	POSTMANS ROAD	PA Pothole - Fill Hole	5,918			006 January 2019	NCTIR	POTFILL
20/66	POSTMANS ROAD	PA Pothole - Fill Hole	4,995			006 January 2019	NCTIR	POTFILL
20/67	MOUNT FYFFE ROAD	Sight Rail New Install	3,484	6		006 January 2019	BAU	
20/84	RED SWAMP ROAD	Allig Crack - Crack Seal	270	5	2	006 January 2019	NCTIR	SEALCRK
20/85	RED SWAMP ROAD	FatigCrack - Digout (Two)	610	120	3	006 January 2019	NCTIR	DIGOUTS
20/86	RED SWAMP ROAD	Deformation - Digout (Two)	714	358	6	006 January 2019	NCTIR	DIGOUTS
20/88	RED SWAMP ROAD	SlipCrk - Stabilise (Two)	1,854	12	11	006 January 2019	NCTIR	STAB
20/89	RED SWAMP ROAD	FatigCrack - Digout (Two)	2,393	11	4	006 January 2019	NCTIR	DIGOUTS
20/90	RED SWAMP ROAD	Depression - Digout (Two)	3,422	1	1	006 January 2019	NCTIR	DIGOUTS
20/91	RED SWAMP ROAD	Depression - Digout (Two)	3,433	1	1	006 January 2019	NCTIR	DIGOUTS
20/92	RED SWAMP ROAD	Depression - R & R (Two)	3,972	5	1	006 January 2019	NCTIR	RIPREMAKE
20/93	RED SWAMP ROAD	Depression - Stabilise (Single)	4,240	6	2	006 January 2019	NCTIR	STAB
20/94	RED SWAMP ROAD	Allig Crack - Crack Seal	4,689	55	5	006 January 2019	NCTIR	SEALCRK
20/153	LUDSTONE ROAD	Shear - Stabilise (Two)	825	24	3	006 January 2019	NCTIR	STAB
20/159	LUDSTONE ROAD	FatigCrack - Stabilise (Two)	1,140	33	3	006 January 2019	NCTIR	STAB
20/166	SOUTH BAY PARADE	Shear - Stabilise (Two)	362	39	2	006 January 2019	NCTIR	STAB
20/167	SOUTH BAY PARADE	Deformation - Stabilise (Two)	430	35	2	006 January 2019	NCTIR	STAB
20/214	SOUTH BAY PARADE	Deformation - Stabilise (Two)	376	30	2	006 January 2019	NCTIR	STAB
20/255	ESPLANADE ROAD	Depression - Levelling (AC)	683	8	3	006 January 2019	EQ Works	LEVEL
20/276	ESPLANADE ROAD	Depression - Levelling (AC)	1,852	2	2	006 January 2019	EQ Works	LEVEL
20/277	ESPLANADE ROAD	Depression - Levelling (AC)	1,944	5	1	006 January 2019	EQ Works	LEVEL
20/291	ESPLANADE ROAD	Deformation - Stabilise (Two)	1,916	30	2	006 January 2019	EQ Works	STAB
20/311	TORQUAY STREET	Deformation - Stabilise (Two)	1,398	11	2	006 January 2019	EQ Works	STAB
20/379	LUDSTONE ROAD	2nd Coat Seal - Single 5 or 6	1,624	20	5	006 January 2019	NCTIR	SURFREP
20/383	LUDSTONE ROAD	Depression - Stabilise (Two)	1,892	11	3	006 January 2019	NCTIR	STAB
20/408	TORQUAY STREET	Deformation - Digout (Two)	1,366	30	5	006 January 2019	EQ Works	DIGOUTS
20/16498	WEST END	Verge Pest Plants (m)	-	1,200		006 January 2019	BAU	VEGETATION
20/16506	PUHI PUHI ROAD	Emergency Slip (m3)	10,976			006 January 2019		EMERGENCY
20/26	KOURA BAY	2nd Coat Seal - Single 5 or 6	5	13	9	007 February 2019		
20/44	POSTMANS ROAD	FatigCrack - Digout (Two)	1,597	19	6	007 February 2019		DIGOUTS
20/45	POSTMANS ROAD	FatigCrack - Digout (Two)	1,655	4	6	007 February 2019	NCTIR	DIGOUTS
20/46	POSTMANS ROAD	Edge Break	1,630	190		007 February 2019		SHLDMMAINT
20/47	POSTMANS ROAD	Low Shoulder	1,630	190		007 February 2019		SHLDMMAINT
20/48	POSTMANS ROAD	FatigCrack - Digout (Two)	1,735	60	6	007 February 2019	NCTIR	DIGOUTS
20/50	POSTMANS ROAD	FatigCrack - Digout (Two)	1,810	5	3	007 February 2019	NCTIR	DIGOUTS
20/51	POSTMANS ROAD	2nd Coat Seal - Two 3/5	1,817	18	6	007 February 2019	NCTIR	SURFREP
20/52	POSTMANS ROAD	Allig Crack - Crack Seal	1,854	8	2	007 February 2019		SEALCRK
20/53	POSTMANS ROAD	2nd Coat Seal - Two 3/5	1,917	30	6	007 February 2019	NCTIR	SURFREP
20/54	POSTMANS ROAD	FatigCrack - Digout (Two)	1,873	30	2	007 February 2019	NCTIR	DIGOUTS
20/56	POSTMANS ROAD	2nd Coat Seal - Two 3/5	1,966	16	6	007 February 2019	NCTIR	SURFREP
20/58	POSTMANS ROAD	FatigCrack - Digout (Two)	1,996	8	3	007 February 2019	NCTIR	DIGOUTS
20/59	POSTMANS ROAD	2nd Coat Seal - Two 3/5	2,049	37	6	007 February 2019	NCTIR	SURFREP
20/62	POSTMANS ROAD	SWC Deepen/Reshape	1,555	615		007 February 2019	BAU	SWCMAINT
20/78	POSTMANS ROAD	Allig Crack - Crack Seal	2,195	8	5	007 February 2019	NCTIR	SEALCRK
20/79	SCHOOLHOUSE ROAD	Culvert Inlet/Outlet Repair	2,866			007 February 2019	BAU	SWSTRUCT
20/138	MILL ROAD	High Shoulder - >1m	523	1,231		007 February 2019	BAU	SHLDMMAINT
20/191	TUI ROAD	FatigCrack - Stabilise (Two)	8	80	6	007 February 2019	BAU	STAB
20/256	YARMOUTH STREET	Deformation - Stabilise (Two)	9	10	10	007 February 2019	EQ Works	STAB
20/257	ESPLANADE ROAD	Depression - Levelling (AC)	766	5	3	007 February 2019	EQ Works	LEVEL
20/259	ESPLANADE ROAD	Depression - Levelling (AC)	780	85	1	007 February 2019	EQ Works	LEVEL
20/281	FYFFE QUAY	Deformation - Stabilise (Two)	81	20	2	007 February 2019	BAU	STAB
20/282	FYFFE QUAY	SWC Deepen/Reshape	7	1,388		007 February 2019	BAU	SWCMAINT
20/284	FYFFE QUAY	Deformation - Stabilise (Two)	864	80	2	007 February 2019	EQ Works	STAB
20/285	FYFFE QUAY	Side Drain Clear/Reshape	706	300		007 February 2019	BAU	SWCMAINT
20/290	FYFFE QUAY	Deformation - Stabilise (Two)	140	10	2	007 February 2019	BAU	STAB
20/306	TORQUAY STREET	Deformation - Stabilise (Two)	181	10	2	007 February 2019	EQ Works	STAB
20/318	YARMOUTH STREET	Depression - Levelling (Chip)	46	1	8	007 February 2019	EQ Works	LEVEL
20/319	YARMOUTH STREET	Depression - Levelling (AC)	87	2	2	007 February 2019	EQ Works	LEVEL
20/320	YARMOUTH STREET	Iso Crack - Crack Seal	94	30	4	007 February 2019	EQ Works	SEALCRK
20/321	TORQUAY STREET	2nd Coat Seal - Two 3/5	299	10	6	007 February 2019	BAU	SURFREP
20/322	KILLARNEY STREET UPPER	Depression - Stabilise (Two)	464	8	2	007 February 2019	EQ Works	STAB
20/326	WHITBY PLACE	Deformation - Stabilise (Two)	76	10	15	007 February 2019	EQ Works	STAB
20/488	BLUE DUCK VALLEY ROAD	Shoulder Scouring	4,055			007 February 2019	EQ Works	SHLDMMAINT
20/515	FACTORY ROAD	Side Drain Clear/Reshape	-	700		007 February 2019	BAU	SWCMAINT
20/16345	MILL ROAD	High Shoulder - >1m	431	1,277		007 February 2019	BAU	SHLDMMAINT
20/34	SCHOOLHOUSE ROAD	Depression - Levelling (AC)	1,355	2	5	008 March 2019	NCTIR	LEVEL
20/36	SCHOOLHOUSE ROAD	Depression - Levelling (AC)	2,150	5	3	008 March 2019	NCTIR	LEVEL
20/37	SCHOOLHOUSE ROAD	Depression - Levelling (AC)	2,175	23	2	008 March 2019	NCTIR	LEVEL
20/41	SCHOOLHOUSE ROAD	Depression - Levelling (AC)	1,823	2	6	008 March 2019	NCTIR	LEVEL
20/42	SCHOOLHOUSE ROAD	Depression - Levelling (AC)	2,009	6	2	008 March 2019	NCTIR	LEVEL
20/43	SCHOOLHOUSE ROAD	Depression - Levelling (AC)	2,319	8	1	008 March 2019	NCTIR	LEVEL
20/137	MILL ROAD	SWC Deepen/Reshape	375	1,573		008 March 2019	BAU	SWCMAINT
20/139	MILL ROAD	Depression - Stabilise (Two)	2,522	30	2	008 March 2019	NCTIR	STAB
20/140	MILL ROAD	Trench - Stabilise (Two)	2,902	4	7	008 March 2019	NCTIR	SURFOPEN
20/141	MILL ROAD	Deformation - Stabilise (Two)	2,999	16	2	008 March 2019	NCTIR	STAB

Contract/ Dispatch	Road	Fault	Start	Length	Width	Programme	Category	Activity
20/142	MILL ROAD	Trench - Stabilise (Two)	3,032	5	7	008 March 2019	NCTIR	SURFOPEN
20/143	MILL ROAD	FatigCrack - Stabilise (Two)	3,194	22	2	008 March 2019	NCTIR	STAB
20/145	MILL ROAD	Deformation - Stabilise (Two)	3,335	44	2	008 March 2019	NCTIR	STAB
20/148	MILL ROAD	SWC Deepen/Reshape	2,030	2,049		008 March 2019	BAU	SWCMAINT
20/149	MILL ROAD	Depression - Stabilise (Two)	644	55	6	008 March 2019	NCTIR	STAB
20/481	PUHI PUHI ROAD	Shoulder Scouring	541	1		008 March 2019	EQ Works	SHLDMMAINT
20/486	BLUE DUCK VALLEY ROAD	Shoulder Scouring	2,475			008 March 2019	EQ Works	SHLDMMAINT